

## Material Handling (P-50 Glue Adhesive)

### **P-50 Glue Adhesive - Always replace the cap after using a bucket of P-50!**

A small amount of water will ruin P-50 contact cement rendering it waste and increase the risk of material failure if used with temporary or permanent tapes.

The following images illustrate the correct and incorrect way to secure the cap on a bucket of P-50.



#### **CORRECT**

The cap is securely in place and the funnel is up to shed water



#### **INCORRECT!**

The cap is missing which allows water to enter the pail of adhesive.

